

Oil Field Environmental Incident Summary

Incident: 20140803105746 **Date/Time of Notice:** 08/03/2014 10:57

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: TIOGA-MADISON UNIT O-143HR

Field Name: TIOGA

Well File #: 209

Date Incident: 8/2/2014

Time Incident: 12:15

Facility ID Number:

County: MOUNTRAIL

Twp: 158

Rng: 94

Sec: 17

Qtr:

Location Description:

Submitted By: Jason Henry

Received By:

Contact Person: Jason Henry
3015 16th Street SW, Suite 20
Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.1 Mile

Distance Nearest Water Well: 0.1 Mile

Type of Incident: Tank Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	125	Barrels			0	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 11/27/2015

Clean Up Concluded: 8/26/2014

Risk Evaluation:

The release occurred above ground and was contained in secondary containment berm around the AST.

Areal Extent:

N/A - release was contained in secondary containment berm around AST.

Potential Environmental Impacts:

There were no potential receptors observed in the immediate vicinity of the release location.

Action Taken or Planned:

The impacted soil inside of the tank berm will be excavated, stockpiled, and transported off-site to a properly permitted disposal facility.

Wastes Disposal Location: At a properly permitted disposal facility.

Agencies Involved:**Updates**

Date: 8/3/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank leak, remained on location within the diking according to the report. NDIC retains oversight.